

Oil Field Environmental Incident Summary

Incident: 20160122113109 **Date/Time of Notice:** 01/22/2016 11:31

Responsible Party: HUNT OIL COMPANY

Well Operator: HUNT OIL COMPANY

Well Name: REDMOND 1-30-19 1

Field Name: CLEAR WATER

Well File #: 19729

Date Incident: 1/21/2016 **Time Incident:** 11:50

Facility ID Number:

County: MOUNTRAIL

Twp: 157

Rng: 89

Sec: 30

Qtr:

Location Description:

Submitted By: Keith Karow

Received By:

Contact Person: Keith Karow
1900 NORTH AKARD STREET
DALLAS, TX 75201-2300

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 900 Feet

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels			1	barrels
Brine					2	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/29/2016

Clean Up Concluded: 1/27/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Spill was caught and clean up started immediately.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/22/2016 ***Status:*** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained within the diking according to the report. NDIC retains oversight.